

HART connection cable for master - slave connection

**Features**


- K-System accessory
- Connection cable for KFD2-HMM-16 to up to 15 KFD0-HMS-16
- 14-pin flat cable

**Function**

The connection cable K-HM14 is used for connection of a HART Multiplexer Master KFD2-HMM-16 to up to 15 HART Multiplexer Slaves KFD0-HMS-16.

The connection cable has 16 connectors and a length of 0.45 m.

**Dimensions**



**Technical data**


**Ambient conditions**

|                     |                             |
|---------------------|-----------------------------|
| Ambient temperature | 0 ... 55 °C (32 ... 131 °F) |
| Relative humidity   | 5 ... 90 %, non-condensing  |

**Mechanical specifications**

|              |                                   |
|--------------|-----------------------------------|
| Connection   |                                   |
| Device       | 16 x IDC female connector, 14-pin |
| Cable length | 0.45 m                            |
| Note         | distance of plugs 3 cm (1.2 inch) |

**Assembly**



Release date 2017-10-19 07:25 Date of issue 2017-10-19 039630\_eng.xml

Refer to "General Notes Relating to Pepperl+Fuchs Product Information".